



H233

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S ☒RT ☒FE ☒ROTATE ☒BIO OIL ☒

Make / Model	2x 135-6	Date:	28/04/2026		
Fleet Number	H 233				
Hour Meter	5609 hrs				
Machine Serviced	250 ☐ 500 ☐ 1000 ☐	Service Computer reset	☐	Service sticker updated ☐	
Service due	5685 hrs				
Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	NIA		Fuel connectors & pipes	✓	
Lifting eye / points	✓		Engine Oil Level	100%	
Cab glass	✓		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	100%	
Tracks	✓		Ad-blue level	100%	
Blade / stabilizers if fitted	NIA		Refuelling Hose - present	✓	
Seat & Seat Belt	✓				
Steering if applicable	NIA				
Brakes as appropriate	NIA				
Bodywork	✓				
Operating Controls	✓				
Warning Lights	✓				
Gauges/Instruments	✓				
Railings / boxing ring	✓				
Fan & other belts / chains	✓				
Fuel cap secured	✓				
Lenses & mirrors	✓				
Rear & 360° cameras	✓				
Horn	✓				
Travel alarm	✓				
Lights / Beacons	✓				
Obvious Leaks	NIA				
Safety pins & bolts	✓				
Floor mats/ Air freshener	✓				
Defects / Service Details / Notes					
ALL CHECKED OVER - ALL GREASED AND CLEANED AROUND - ALL IN WORKING ORDER -					
Engineers name: KC			Signature: [Signature]		