



PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S ☒RT ☒FE ☒ROTATE ☒BIO OIL ☒

Make / Model	2455	Date:	28.07.2026		
Fleet Number	261				
Hour Meter	2578 hrs				
Machine Serviced	250 ☐ 500 ☐ 1000 ☐	Service Computer reset	☐	Service sticker updated ☐	
Service due	2624 hrs				
Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	/		Fuel Level	100%	
Cab Guards/Covers	X14		Fuel connectors & pipes	100%	
Lifting eye / points	/		Engine Oil Level	100%	
Cab glass	/		Coolant Level	100%	
Chassis bolts & security	/		Hydraulic fluid level	100%	
Seat secure & fully adjustable	/		Washer fluid level	100%	
Tracks	/		Ad-blue level	1.7	
Blade / stabilizers if fitted	/		Refuelling Hose - present	1.7	
Seat & Seat Belt	/				
Steering if applicable	X14				
Brakes as appropriate	X14				
Bodywork	/				
Operating Controls	/				
Warning Lights	/				
Gauges/Instruments	/				
Railings / boxing ring	X14				
Fan & other belts / chains	/				
Fuel cap secured	/				
Lenses & mirrors	/				
Rear & 360° cameras	X14				
Horn	/				
Travel alarm	/				
Lights / Beacons	/				
Obvious Leaks	/				
Safety pins & bolts	/				
Floor mats/ Air freshener	/				

Electric		
Cable Connections	/	
General Cleanliness	/	
Battery Security	/	

Other Checks		
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes

ALL CHECKS DONE, CREAMED AROUND GREASED AROUND
ACIN WORKING ORDER

Engineers name:

GA BAUER 1,

Signature: